Printed on: 2/17/2013 4:30:37 PM

						1 1111100	1011 . 2/17/2013 4.30.37 1 10		
National Transportation Safety Board	ID:	DCA05MA0 ⁻	11	Aircraft Registration Number: N85VT					
FACTUAL REPORT	Occur	Occurrence Date: 11/22/2004				Most Critical Injury: Fatal			
AVIATION OC			Occurrence Type: Accident			Investigated By: NTSB			
Location/Time									
Nearest City/Place	State	State Zip Co		Local Time	Time Zone				
Houston	TX			0615	CDT				
Airport Proximity: Off Airport/Airstrip	Distance From	nnce From Landing Facility: 4							
Aircraft Information Summary									
Aircraft Manufacturer			Model/Series	5	Type of Aircraft				
Gulfstream Aerospace		G-III		Airplane					
Revenue Sightseeing Flight: No Air Medical Transport Flight: No									

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

*** Note: NTSB investigators traveled in support of this investigation and used data obtained from various sources to prepare this aircraft accident report. ***

The Safety Board's full report is available at http://www.ntsb.gov/publictn/publictn.htm. The Aircraft Accident Brief number is NTSB/AAB-06/06.

On November 22, 2004, about 0615 central standard time, a Gulfstream G-1159A, N85VT, operated by Business Jet Services Ltd., struck a light pole and crashed about 3 miles southwest of William P. Hobby Airport, Houston, Texas, while on an instrument landing system approach to runway 4. The two pilots and the flight attendant were killed, an individual in a vehicle near the airport received minor injuries, and the airplane was destroyed by impact forces. The airplane was being operated under the provisions of 14 Code of Federal Regulations Part 91 on an instrument flight rules flight plan. Instrument meteorological conditions prevailed at the time of the accident.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA05MA011

Occurrence Date: 11/22/2004

AVIATION	l	Occurrence Type: Accident									
Landing Facility/Approach In	formation	-									
Airport Name		Airp	ort ID:	Airport Elevation	Run	way Used	Runwa	tunway Length		way Width	
Houston Hobby Airport	Hobby Airport KHOU 45 Ft. MSL 4 760						7602		150	0	
Runway Surface Type: Concrete											
Runway Surface Condition:											
Approach/Arrival Flown: ILS											
VFR Approach/Landing:											
Aircraft Information											
Aircraft Manufacturer		l	Model/	/Series					Number		
Gulfstream Aerospace			G-III					449			
Airworthiness Certificate(s): Norm	ıal										
Landing Gear Type: Retractable	- Tricycle										
Amateur Built Acft? No									er of Engines: 2		
Engine Type: Turbo Fan	inufacturer: yce		Model/Se 511-8	eries:		I	ted Power: 400 LBS				
- Aircraft Inspection Information											
Type of Last Inspection		Date of Last Inspection Time Since Last Inspection						Airframe T	otal Time		
Continuous Airworthiness	10	0/2004			,	28.8 Ho	ours	85	565.8 Hours		
- Emergency Locator Transmitter (I	ELT) Information										
ELT Installed?/Type Yes /		EL	Γ Operat	ted? Yes	ELT Aic	ded in Locatin	ng Accide	ent Site?)		
Owner/Operator Information											
Registered Aircraft Owner			Street A	Address 3315 N. Mem	orial Dr	. Hangar 3	31				
The Jet Place, Inc.		City							Zip Code 74115		
			Street A						ОК		
Operator of Aircraft		_		3315 N. Mem	orial Dr.	. Hangar 3	31				
The Jet Place, Inc.	City							Zip Code 74115			
Tulsa OK 74115 Operator Does Business As: Operator Designator Code:									•		
- Type of U.S. Certificate(s) Held:											
Air Carrier Operating Certificate(s):	: Commuter Air Ca	arrier									
Operating Certificate:				Operator Certific	cate:						
Regulation Flight Conducted Under: Part 91: General Aviation											
Type of Flight Operation Conducted	d: Positioning										
		FACTUAI	REPO	RT - AVIATION						Page 2	

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA05MA011

Occurrence Date: 11/22/2004

	AVIATI	Occurrence Type: Accident											
First Pilot Information													
Name		City				St	ate	Date of Birth	Age				
On File									67				
Sex: M Seat Occupied: Occupational Pilot? Certificate Number: On File													
Certificate(s): Airline Transport													
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA:													
Instrument	Rating(s): Airpl	ane											
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane													
Current Bie	nnial Flight Revie	∍w? 05/2004	4										
Medical Ce	ert.: Class 1	Medica	al Cert. Status	3:					Date of	Last N	/ledical E	xam: 06/2004	
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nię	Night Instru Actual			rument Simulated		Glider	Lighter Than Air
Total Time		19000	1000										
Pilot In Con	mmand(PIC)	15700											
Instructor						+							
Instruction I						+-							
Last 90 Day		90				+-							
Last 30 Day		0			 	+-							
Seatbelt Us		<u> </u>	I I ulder Harness	Used?	<u> </u>		Toxico	oloav Pe	formed?		Se	econd Pilot? Ye	<u></u>
	n/Itinerary												
	ght Plan Filed: [F												
Departure F							Ctoto		Airport Ident	ifior	Dono	rturo Timo	Time Zone
DALLAS	<u>om</u>						State TX		DAL	illei	Departure Time 0540		CST
Destination	1						State		Airport Ident	ifior			
Same as Accident/Incident Location State Airport Identifier													
Type of Clearance: IFR													
Type of Airspace: Class B													
Weather Information													
Source of \	Wx Information:												
National Weather Service													
				FACTUAL	REPORT	' - AVI.	ATION	J					Page 3

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: DCA05MA011

Occurrence Date: 11/22/2004

AVIATION			Occur	Occurrence Type: Accident								
Weather Information												
WOF ID	Observation Time	Time Zone	WOF Ele	evation	WOF Di	istance From	n Accid	lent Site		Direction From Accident Site		
				I								
KHOU	0615	CST	4!	5 Ft. MSL				4 NM			45 De	eg. Mag.
Sky/Lowes	st Cloud Condition:					Ft. AG	iL	Condition o	of Ligh	nt: Dawn		
Lowest Ce	eiling: Broken		100) Ft. AGL	Visibi	Visibility: 0.13 SM				meter:	30.01	"Hg
Temperatu	ure: 22 °C [Dew Point:	21 °	°C Weath	ner Condi	tions at Acci	ident S	ite: Instrum	ent C	Conditions		
Wind Direc	otion: 90	Wind Spe	ed: 3		Winc	d Gusts:						
Visibility (R	RVR): 1600 Ft.	Visibility ((RVV)	SM								
Precip and	d/or Obscuration:											
^ coidont	Information											
Accident Information												
Aircraft Dar	mage: Destroyed		Aircraft	Aircraft Fire: Ground					olosior	<u> </u>		
- Injury Sur	mmary Matrix	Fatal	Serious	Minor	None	TOTAL						
First Pi	ilot	1				1						
Second	d Pilot	1				1						
Studen	nt Pilot											
Flight I	nstructor											
Check	Pilot											
Flight E	Engineer											
Cabin /	Attendants	1				1						
Other C	Crew											
Passen	ngers											
- TOTAL /	ABOARD -	3				3	1					
Other C	Ground						1					
- GRANE	O TOTAL -	3				3	1					

National Transportation Safety Board

NTSB ID: DCA05MA011

FACTUAL REPORT	Occurrence Date: 11/22/2004								
AYIATION	Occurrence Type: Accident								
Administrative Information									
Investigator-In-Charge (IIC)									
Frank Hilldrup									
Additional Persons Participating in This Accident/Incide	ent Investigation:								